





CALCIANO




1656/CALCIANO/2606/25/

A




2/6

1656/CALCIANO/2606/25/



3/6

1656/CALCIANO/2606/25/



1

B1 x 1	B2 x 1	B3 x 1	B4 x 1	1 M8 x 35 x 2	2 M8 x 15 x 2	5 x 1
-----------	-----------	-----------	-----------	------------------------	------------------------	----------

Diagram showing the assembly of the legs (B1, B2, B3, B4) to the base plate (A) using screws (1, 2) and a corner bracket (5).

A x 1	B1 x 1	B2 x 1	B3 x 1	B4 x 1	C x 1
D x 1	1 M8 x 35 x 2	2 M8 x 15 x 2	3 M6 x 50 x 4	4 M6 x 35 x 4	5 x 1

2

C x 1	D x 4	3 M6 x 50 x 4	5 x 1
----------	----------	------------------------	----------

Diagram showing the assembly of the crossbar (C) and support bars (D) to the legs (B1, B2, B3, B4) using screws (3, 4) and a corner bracket (5).

3

A x 1	4 M6 x 35 x 4	5 x 1
----------	------------------------	----------

Diagram showing the final assembly of the frame (A, B1, B2, B3, B4, C, D) using screws (4) and a corner bracket (5).