



No.		Qty	No.		Qty
E	© M 6*30	2	E1	© — M6*35	12
E2	M6*20	8	F	(i) M6	24
G	P	2	Н	\$4-M6	1


		F	ASSEMBLY	INSTRUCT	ION
No.		Qty			No.
1		1			E
2		1			E1
3		1			
4		1			E2
5		1			F
6		1			G
7		2			
8		1			H
9	Æ)	1			


No.		Qty
E	M6*30	2
E1	M6*35	12
E2	© — M6*20	8
F	© M6	24
G		2
Н	\$4-M6	1

PAGE 2/3












	AS	SEMBLY	INSTRUCTIO	NC
No.	Qty			No
1	1			Е
2	1			
3	1			Ε
4	1			Ε
5	1			F
6	1			G
7	2			1
8	1			
9	1		latana	

No.		Qty
Е	(1)	2
<u> </u>	M6*30	
E1	(a) manage	12
	M6*35	12
E2		8
	M6*20	0
F	0	24
I	M6	4
G		2
H	\$4-M6	1
	ÿ 34-IVIU	
	_	

PAGE 3/3









PLEASE KINDLY NOTE THAT AFTER ASSEMBLED, THEN TIGHTEN ALL THE SCREWS! IF YOU FEEL IT'S HARD TO SCREW IN, PLEASE TAKE BACK A LITTLE , THEN TRY AGAIN!


step4


ASSEMBLY INSTRUCTION

PAGE 1/2



No.		Qty	No.		Qty
Е	© m M6*30	4	E1	© — M6*35	12
F	(i) M6	16	G	\$4-M6	1





No.		Qty	No.		Qty
E	M6*30	4	E1	M6*35	8
F	(i) M6	16	G	P	4
Н	\$4-M6	1			

