



LATTES
















An icon showing an L-shaped metal bracket inside a circle, and a power drill with a diagonal line through it, indicating that a power drill should not be used.	A warning triangle icon with an exclamation mark inside.	A clock icon showing a 30-minute duration.
An icon showing a cushion on a base inside a circle, and a screw being inserted into a cushion with a diagonal line through it, indicating that screws should not be used to secure the cushion.	A warning triangle icon with an exclamation mark inside.	An icon of a person, representing the number of people required for assembly.

30'







2

A	B	C	D	E
				
x 1	x 1	x 1	x 1	x 1




2 x 4



1	2	3	4	5	6
				 M8 x 55	
x 4	x 4	x 4	x 1	x 4	x 4


1

A





x 1

D



x 1



2

B





x 1

C



x 1



3

2




x 4


3




x 4




2




2



2



2




4

1




x 4




2





2



2




2




5

4



x 1


5





M8
x
55

x 4

6



x 4



6

E



x 1

