


MINOZZO










Diagram illustrating assembly instructions and safety warnings:

- Warning 1:** A warning triangle with an exclamation mark is shown above a box containing an L-shaped metal bracket and a crossed-out power drill icon, indicating that a power drill should not be used for this part.
- Warning 2:** A second warning triangle with an exclamation mark is shown above a box containing a rectangular foam cushion and a crossed-out icon of a cushion being cut, indicating that the cushion should not be cut.
- Time:** A clock icon with a circular arrow indicates a 30-minute assembly time.
- Personnel:** An icon of a person indicates that 1 person is required for assembly.

A




1




x 8

2






x 8

3






x 1




1






B x 2







1





2





3





4




5



C




D




x 2

E




x 1

F




x 1

G




x 2

H



x 2


1



M6
x
20


x 8

2




x 13

3



x 2


4



M6
x
60


x 4

5



x 4





6






M6
x
50

x 1






1





2



3



4



5

