



# GELDO






Tools and materials required for the assembly:

- Icon box 1: Pencil, marker, tape measure, and power drill. Includes a warning triangle.
- Icon box 2: A rectangular block being placed on a surface and another block being cut with a saw. Includes a warning triangle.


Estimated time: 20'

Number of people: 1


**B**



**A**




**A**








**x 1**

**B**




**x 1**


1





!



!



2



3

