












A	 $\Phi 8 \times 30 \text{mm}$	24
B	 M6*90mm	12
C		12
D	 M6*140	3
E	 M6	14
F	 M6*100mm	1
G		2
H	 $\Phi 4 \times 30 \text{mm}$	56
I	 M6*80mm	7


J		12
K		12
L	 840mm	2
M	 $\Phi 7 \times 50 \text{mm}$	8
N	 3*16	16
O	 35 mm	8
P	 45 mm	14
Q	 4 mm	1




STEP:1




STEP:2




STEP:3




STEP:4



STEP:5




STEP:6




H		Φ4*30mm	26
---	---	---------	----

STEP:7





J		12
K		12

STEP:8





STEP:9




L		840mm	2
---	--	-------	---

STEP:10



M		Φ7*50mm	8
---	---	---------	---

STEP:11



STEP:12

