























Assembly Instructions


1  X2	2  X2	3  X2	4  X2	5  X2
6  X1	7  X1	8  X1	9  X1	10  X2
11  X1	12  X1	13  X1	14  X1	15  X1
16  X3	17  X1	18  X1	19  X1	

A  X12	B  X12	C  6x30mm X16	D  3x25mm X16	E  3x12mm X20	F  X4	G  X2	H  X2
I  X4	J  2.5x12mm X4	K  4x25mm X2	L  X2	M  3x16mm X8	N  4x30mm X1	O  X2	


Step 1




Step 2




Step 3




Step 4




Step 5



Step 6



Step 7



Step 8

