



# BECKLEY











Assembly instructions for the shelving unit, including tool requirements, time, and personnel.

**Tools:** A circular icon contains a screwdriver and an L-shaped Allen key. To the right is a power drill. A warning triangle with an exclamation mark is positioned above these icons.


**Time:** A clock icon is shown with the number **30'** below it, indicating the estimated assembly time.

**Personnel:** A stick figure icon is shown with the number **2** below it, indicating that two people are required for assembly.




|   |   |   |  |   |
|---|---|---|--|---|
| <p><b>1</b></p>  <p><b>x 1</b></p> | <p><b>2</b></p>  <p><b>x 1</b></p> | <p><b>3</b></p>  <p><b>x 2</b></p> | <p><b>4</b></p>  <p><b>x 1</b></p> | <p><b>5</b></p>  <p><b>x 2</b></p> |
|---|---|---|--|---|

6




x 1

7




x 1

8




x 1

9




x 1

A



x 6

B




x 16

C




x 12

D




x 2

E




x 1

F




x 1

G



x 1

H



x 1

I




x 1

J








x 1

K






x 1




1





2








3











4



5




6






7

C






D



8

C








9

J



x 1




10

I




x 1

H



x 1

K



x 1

