


Exploded view diagram of the 1000mm wide cabinet showing 17 numbered components. The diagram includes a coordinate system with X, Y, and Z axes. The components are: 01 (top panel), 02 (right side panel), 03 (bottom panel), 04 (top rail), 05 (top rail), 06 (top rail), 07 (bottom rail), 08 (top rail), 09 (top rail), 10 (bottom panel), 11 (bottom rail), 12 (top rail), 13 (top rail), 14 (top rail), 15 (top rail), 16 (top panel), 17 (bottom panel).



	A  X37+1pcs	B  X37+1pcs	C  X24+1pcs	D  ST-0030mm x2pcs
E ST4*14mm  x19+1pcs	F 350mm  x2pcs	G 350mm  x2pcs	H ST4*25mm  x 4pcs	I  x 1pcs
J  x 1pcs				



1

A  x12pcs

D  x2pcs

01

02

90°
10mm

x 2pcs

A
x12pcs

2

F  350mm x2pcs

G  350mm x2pcs

E  ST4*14mm x12pcs

01

02

G x 2pcs

F x 2pcs

