



VORGOD





An L-shaped bracket icon inside a circle, next to a power drill icon with a diagonal line through it, indicating that drilling is not required.

A warning triangle icon with an exclamation mark.

A clock icon with a circular arrow, indicating a 10-minute assembly time.




An icon showing a rectangular block sitting on a base with diagonal lines, next to a crossed-out icon of a block with a screw being inserted, indicating that screws are not used.

A warning triangle icon with an exclamation mark.


An icon of a person, indicating that two people are required for assembly.

1/3



712/VERGOD/120625/



!



1

A	B	C	D	E
				
x 1	x 5	M4 x 30 x 20	x 1	x 20

