



1/9






60'



1

1914/MORLEY/070922/





2/9

1914/MORLEY/070922/

1 x 2	2 x 4	3 x 2
4 x 15	5 x 4	6 x 6
7 x 1	8a x 2	8b x 2

3/9


1914/MORLEY/070922/





4/9

1914/MORLEY/070922/



3






5



4



6






5/9

1914/MORLEY/070922/



6/9

1914/MORLEY/070922/



7





9



8



10



7/9



1914/MORLEY/070922/

8/9

1914/MORLEY/070922/

11

1 x 2	5 M4 x 22 x 4	6 x 4	7 x 1
----------	---------------------------	----------	----------



12

8a x 2	8b x 2	7 x 1
-----------	-----------	----------

