



MIRANDE






Assembly instructions for the bed frame, including tool requirements, time, and personnel.


Tools: An icon shows an Allen key and a wrench inside a circle, with a crossed-out power drill icon next to it. A warning triangle is positioned to the right of this icon set.

Time: An icon of a clock with a circular arrow indicates a duration of **40'**.


Personnel: An icon of a person and the number **2** indicate that two people are required for assembly. A warning triangle is positioned to the left of this icon set.



1




6 x 26



4

9



4

2


9



9



9




5



3 x 2




1



x 1

2




x 1

3




x 2

4




x 2

5




x 1

6



x 26

7




x 13

8




x 26

9




x 4

A




x 16

B




x 4

C




x 4

D




x 8

E



x 20

F






x 1

G






x 1




1






2





3




4



5 x 13



!



6

