







TIMMINS




1/11

2545/TIMMINS/050225/







2/11

2545/TIMMINS/050225/



3/11

2545/TIMMINS/050225/







4/11

2545/TIMMINS/050225/

5/11

2545/TIMMINS/050225/



6/11

2545/TIMMINS/050225/

7/11

2545/TIMMINS/050225/

9 x 2

11

x 1

11

6

10

7

11 x 2

12

x 1

B

M4

x 30

x 4

12

6

10

7

12

B

10 x 2

8

x 1

H

M4

x 25

x 6

11

6

10

7

8

H

12 x 2

K2

x 1

L2

x 1

C

M3

x 12

x 4

1

2

K2

12

10

1

2

L2

1

2

C

13 x 2

C

M3

x 12

x 2

J

x 1

10

12

6

7

J

C

15

C

M3

x 12

x 8

1a

1b

1c

1d

1

2

7

14

1

2

7

1

2

7

1

2

7

10/11

2545/TIMMINS/050225/

11/11

2545/TIMMINS/050225/