





MARNOO












Diagram illustrating assembly instructions and safety warnings:

- Top Warning:** A crossed-out power drill icon indicates that power tools should not be used. To the right is a warning triangle with an exclamation mark.
- Time:** A clock icon indicates a 10-minute assembly time.
- Bottom Warning:** A crossed-out icon of a block being lifted by a hand indicates that the table should not be lifted by the top. To the right is a warning triangle with an exclamation mark.
- Person:** An icon of a person indicates that 1 person is required for assembly.



<p>A</p> 	<p>B</p> 	<p>C</p> 	<p>D</p> 
<p>x 1</p>	<p>x 3</p>	<p>x 1</p>	<p>x 3</p>

1



2

