


ARIZONA
























Diagram illustrating assembly instructions and safety warnings:

- Top Section:** Shows a circular icon containing a screwdriver and an L-shaped bracket. To the right is a crossed-out power drill icon. A warning triangle with an exclamation mark is positioned above this section.
- Bottom Section:** Shows a circular icon containing a rectangular block being placed on a textured surface. To the right is a crossed-out icon of a block with a diagonal line through it. A warning triangle with an exclamation mark is positioned above this section.
- Timing:** A clock icon is shown to the right of the top section, with the text "60'" below it, indicating a 60-minute assembly time.
- Personnel:** A person icon is shown to the right of the bottom section, with the number "2" below it, indicating that two people are required for assembly.





A




x 30

B




x 22

C




x 22

D




x 14

E




x 20

F




x 8

G




x 10

H



x 2

I




x 12

J




x 14

K




x 4

L




x 24

M



x 5

N




x 5

O




x 4

P




x 1

Q




x 2

CL




x 3

CR




x 3

DL




x 3

DR



x 3

R




x 4

S




x 2

T




x 2

U





x 2

V





x 1

1




2



3

4




x 1


C




x 2




1a



1c



1b





4



D






x 6





5





6







7






8





9






10




11



12





13



14

H
M4
x
50
x 2






15

C



x 8



16

I






x 12






J






x 12



17 x 2




18





19

L



x 16





20



O






x 4



21




22 x 3



23 x 3

16





x 1

B



x 4




24 x 3

M





x 1



N




x 1



25 x 3



26 x 3




27 x 3


C




x 4



1a



1b




28 x 3

A




x 4

DL




x 1


DR




x 1



14



29



30

