




SPENCER







Beliani

1/16

Beliani

1192/SPENCER/210623/



2/16





Beliani

1192/SPENCER/210623/

3/16

Beliani

1192/SPENCER/210623/







4/16

Beliani
1192/SPENCER/210623/

5/16

Beliani
1192/SPENCER/210623/







6/16

Beliani
1192/SPENCER/210623/

7/16

Beliani
1192/SPENCER/210623/



8/16





Beliani

1192/SPENCER/210623/

9/16

Beliani

1192/SPENCER/210623/



10/16

Beliani


1192/SPENCER/210623/

11/16


Beliani

1192/SPENCER/210623/


17




19



18



20




12/16

Beliani
1192/SPENCER/210623/


13/16

Beliani
1192/SPENCER/210623/


21




23



22



24





14/16

Beliani
1192/SPENCER/210623/

15/16

Beliani
1192/SPENCER/210623/

25



26

