


GIAVENO












Diagram illustrating assembly instructions and safety warnings:




- Warning 1:** A warning triangle with an exclamation mark is positioned above a box containing an L-shaped metal bracket and a crossed-out power drill icon, indicating that a power drill should not be used for this step.
- Warning 2:** A second warning triangle with an exclamation mark is positioned above a box containing a rectangular wooden block being placed on a slatted surface and a crossed-out icon of the block being placed on a flat surface, indicating that the block must be placed on the slatted surface.
- Time:** A clock icon with a circular arrow indicates a duration of **15'** (15 minutes).
- Personnel:** An icon of a person indicates that **1** person is required for this step.







1



2



3



4

