



A		M6*90	8
B			8
C		Φ6*70	12
D		Φ6*90	4
E		Φ7*60	6
F		Φ8*30	8
G		4*30	52
H			1


STEP:1




STEP:2




STEP:3




STEP:4




STEP:5






A		12	
B		1510	12
C		35 mm	8
D		3 x 16	16
E		Ø8 x 30	4
F		Ø7 x 50	8
N		700 mm	2
J		4 mm	1

STEP:1



STEP:2


X2



A		12
C		8
D		16
E		4

STEP:3

X2



B		12
N		2
F		8